

	Type	Hits	Search Text	DBs
1	BRS	295	(conduit or cable) near bushing	USPAT
2	BRS	249	((conduit or cable) near bushing) and (passage or opening)	USPAT; US-PGPUB
3	BRS	2	5410102.URPN.	USPAT
4	BRS	7	("1845699" "3435128" "3779078" "4358632" "4487995" "4547623" "5012042").PN.	USPAT
5	BRS	6	((conduit or cable) near bushing) and (passage or opening)) and (paint or wallpaper)	USPAT; US-PGPUB

	Time Stamp	Comments	Error Definitio n	Errors
1	2003/03/31 15:44			0
2	2003/03/31 16:50			0
3	2003/03/31 16:05			0
4	2003/03/31 16:05			0
5	2003/03/31 16:51			0

	Type	Hits	Search Text	DBs
1	BRS	5222	248/68.1 or 248/74.1 or 248/74.3 or 248/74.2 or 248/74.4 or 248/62	USPAT
2	BRS	0	6517032.URPN.	USPAT
3	BRS	10	("2466247" "3051424" "3273838" "3363865" "4252289" "4783029" "5110074" "5961081" "6138960" "6164604").PN.	USPAT
4	BRS	0	6513766.URPN.	USPAT
5	BRS	10	("2417261" "2972461" "3051424" "3432129" "3913187" "4317262" "4439896" "4609171" "4674720" "5639049").PN.	USPAT
6	BRS	28	4317262.URPN.	USPAT
7	BRS	12	("3086265" "3088702" "3090826" "3157377" "3475716" "3516631" "3517702" "3529795" "3542321" "3900923" "3942750" "3954238").PN.	USPAT
8	BRS	1185	24/278 or 24/279 or 24/274WB	USPAT
9	BRS	7	"3273838"	USPAT
10	BRS	4	3273838.URPN.	USPAT

	Time Stamp	Comments	Error Definitio n	Errors
1	2003/03/28 15:30			0
2	2003/03/28 15:11			0
3	2003/03/28 15:11			0
4	2003/03/28 15:14			0
5	2003/03/28 15:14			0
6	2003/03/28 15:15			0
7	2003/03/28 15:16			0
8	2003/03/28 15:31			0
9	2003/04/01 13:43			0
10	2003/04/01 13:43			0